




## UNC Hex Coupling (Connector) Nuts

Also known as a long nut, these coupling or connector nuts are typically employed in joining sections of threaded bar/studding together where required.



<b>d</b>	<b>tpi</b>	<b>m</b>	<b>s</b>
1/4	20	7/8	3/8
5/16	18	1	7/16
3/8	16	1 - 1/8	1/2
7/16	14	1 - 1/4	5/8
1/2	13	1 - 1/4	9/16
5/8	11	1 - 3/4	7/8
3/4	10	2	1
7/8	9	2 - 1/2	1 - 1/4
1	8	2 - 1/2	1 - 3/8
1 - 1/8	7	3	1 - 1/2
1 - 1/4	7	3	1 - 5/8
1 - 1/2	6	3 - 1/2	2